



01272.020659.

cgfe
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: S. Riley
MASAYASU TOMIYAMA)	
	:	Group Art Unit: 2838
Appl. No.: 10/782,996)	
	:	
Filed: February 23, 2004)	
	:	
For: OVERVOLTAGE FLY-BACK)	
RESONANT-TYPE CONVERTER	:	
)	
U.S. Patent No.: 7,023,679 B2	:	
)	
Issued: April 4, 2006	:	November 28, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate

DEC 04 2006

of Correction

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/30/2006 SZENDIE1 00000056 7023679

01 FC:1011

100.00 00

DEC - 5 2006

Patentee's undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,



Edward A. Kmett
Attorney for Patentee
Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 121112v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,023,679 B2

DATED : April 4, 2006

INVENTOR(S) : Masayasu Tomiyama

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 18, "As" should read -- In --; and

Line 46, "to" should be deleted.

COLUMN 7:

Line 32, "place" should read -- placed --.

COLUMN 8:

Line 45, "a output" should read -- an output --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,023,679 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
121111 (Form#30)



DEC - 5 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,023,679 B2

DATED : April 4, 2006

INVENTOR(S) : Masayasu Tomiyama

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 18, "As" should read -- In --; and

Line 46, "to" should be deleted.

COLUMN 7:

Line 32, "place" should read -- placed --.

COLUMN 8:

Line 45, "a output" should read -- an output --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,023,679 B2

No. of add'l. copies
@ 30¢ per page

DEC - 5 2006